

ND NORSK DATA	ENGINEERING CHANGE ORDER		PAGE 1 OF 2.
	ECO NO.: 100-773		
VALID FOR	PART NOs. : 324534 VERSIONS : GB,GC,GE,GG NAME : ETHERNET II PRINT NOs.: 3094 ND NOs. : --		
NEW VERSION	PART NOs. : 324534 VERSIONS : HB,HC,HE,HG NAME : ETHERNET II		
SYMPTOMS	<u>DESIGN ERROR:</u> CP 121 might short 12V to ground.		
COMPO- NENTS Capasitor	REMOVE: 1 pc. 47 uF (10V)	INSERT: 1 pc. 47 uF (16V) p/n 503823	
VALIDITY	X EQUIPMENT IN PRODUCTION X FUTURE PRODUCTION * FIELD ACTION		
RESPONS- IBILITY	APPROVED BY: GHL ----- DATE: 900103 -----	REVISION: ISSUED BY: --- ----- DATE: -----	

- ND ServiceTeam -

ND NORSK DATA	ENGINEERING CHANGE ORDER	PAGE 2 OF 2.
PART NO.: 324534 GB,GC,GE,GG > HB,HC,HE,HG ECO NO.: 100-773		
ISSUED	DATE: 891206	BY (INITIALS): AMA

Remove capasitor CP121 47uF (10V) 1x. 6y - 1x. 8y (9A)
 Insert capasitor CP121 47uF (16V) 1x. 6y - 1x. 8y (9A)