

ND Service- Team	ENGINEERING CHANGE ORDER		PAGE 1 OF 2.
	ECO NO.: 100-783		
VALID FOR	PART NOS. : 324534//45400 VERSIONS : LB,LC,LE,IG//B NAME : ETHERNET II PRINT NOS.: 3094 ND NOS. : —		
NEW VERSION	PART NOS. : 324534//45400 VERSIONS : MB,MC,ME,MG//C NAME : ETHERNET II		
SYMPTOMS	<u>FATAL:</u> <u>SINTRAN ERROR MESSAGE:</u>  Memory Out of Range.  Memory Parity Error.		
COMPO- NENTS	REMOVE:	INSERT:	
PAL	1 pc. 45400 B	1 pc. 45400 C p/n 30045400	
VALIDITY	X      EQUIPMENT IN PRODUCTION  X      FUTURE PRODUCTION  *      FIELD ACTION		
RESPONS- IBILITY	APPROVED BY:    GHL DATE:              920218	REVISION:        _____ DATE:              _____	ISSUED BY:        _____

- ND ServiceTeam -

ND ServiceTeam	ENGINEERING CHANGE ORDER	PAGE 2 OF 2.
PART NO.: 324534//45400 LB,LC,LE,IG//B > MB,MC,ME,MG//C		ECO NO.: 100-783
ISSUED	DATE: 920129	BY (INITIALS): AMA

Insert new PAL 45400 C in pos. 24D.

EN2-REFRESH (PAL)

A	POS	B	C	D	E	F	G	H	J	K	L	M	N	P	Q	R
45400	24D	B	C													
ECO 100-		777	783													