

ND Service- Team	ENGINEERING CHANGE ORDER		PAGE 1 OF 2.
			ECO NO.: 100-784
VALID FOR	PART NOS. : 322626 / 066XX VERSIONS : LC / L NAME : GPIB CONTROLLER PRINT NOS.: 3026 ND NOS. : --		
NEW VERSION	PART NOS. : 322626 / 066XX VERSIONS : MC / P NAME : GPIB CONTROLLER		
SYMPTOMS	<u>DESIGN ERROR:</u> May give various errors as: ERROR 70, ERROR 72, ERROR 73		
COMPO- NENTS	REMOVE: FROM 1 pc. 06600 L 1 pc. 06601 L 1 pc. 06602 L	INSERT: 1 pc. 06600 P 1 pc. 06601 P 1 pc. 06602 P	
VALIDITY	X EQUIPMENT IN PRODUCTION X FUTURE PRODUCTION * FIELD ACTION		
RESPONS- IBILITY	APPROVED BY: LB/RV DATE: 920326 _____	REVISION: _____ ISSUED BY: _____ DATE: _____	

- ND ServiceTeam -

ND ServiceTeam	ENGINEERING CHANGE ORDER	PAGE 2 OF 2.
PART NO.: 322626 / 066XX LC / L > MC / P ECO NO.: 100-784		
ISSUED	DATE: 910507	BY (INITIALS): AMA

Insert new PROM 06600 P in pos. 23G. (Last ECR version P 37)
 Insert new PROM 06601 P in pos. 25G. (Last ECR version P 37)
 Insert new PROM 06602 P in pos. 27G. (Last ECR version P 37)

GP1B-MICRO PROGRAM 2K x 8 EPROM

A	POS	B	C	D	E	F	G	H	J	K	L	M	N	P	Q	R
0 6 6 0 0	23G	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX	H	J	-	L	-	-	P		
0 6 6 0 1	25G	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX	H	J	-	L	-	-	P		
0 6 6 0 2	27G	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX	H	J	-	L	-	-	P		
ECO 100-								321	418		576			584		