



ND NORSK DATA	ENGINEERING CHANGE ORDER		PAGE 1 OF 3.
			ECO NO.: 100-778
VALID FOR	PART NOs. : 350232 VERSIONS : AA NAME : DMA/APS ADAPTER PRINT NOs.: 1702 ND NOs. : --		
NEW VERSION	PART NOs. : 350232 VERSIONS : BA NAME : DMA/APS ADAPTER		
SYMPTOMS	<p><u>PRINT ERROR:</u></p> <p>Missing connection.</p>		
COMPO- NENTS	REMOVE:	INSERT:	
VALIDITY	X EQUIPMENT IN PRODUCTION X FUTURE PRODUCTION - FIELD ACTION		
RESPONS- IBILITY	APPROVED BY: AANO DATE: 900613 -----	REVISION: ISSUED BY: DATE: ----- -----	

NORSK DATA	ENGINEERING CHANGE ORDER	PAGE 1 OF 1
PART NO.: 350232 AA > BA ECO NO.: 100-778		
ISSUED	DATE: 890313	BY (INITIALS): AMA

Connect

(U1/ 8 - U4/ 8)



 NORSK DATA A.S Oslo , Norway	Sheet 1 of 1
	Id.no. : 350232 A A2 Print no.: 1702 A2
DMA/APS ADAPTER	Design: STLI Drawn: BW Date :880909
Drg.no.: —	Issue: —

NOTE!

Connector A and B are to be mounted on solder side.